


# CORNER RECORD

BK 31 Pg 11  
CR 819

Document Number \_\_\_\_\_

City of Oakland County of Alameda, California

Brief Legal Description Lot 9, Block 25, Tract 509 (10M34)



## CORNER TYPE

Government Corner ☐ Control ☐  
 Meander ☐ Property ☒  
 Rancho ☐ Other ☐  
 Date of Survey July 16, 1996

## COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found ☒ Found and tagged ☐ Established ☒ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found monuments in Bywood Drive as shown on the map of Tract 509 (10M34). Found  
cross chiseled in concrete curb on extension of Lot Line.

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_


Set 1/2" rebar with plastic cap L.S.6745 as shown on sketch.

Set 2"x2" wood hub with 1/2" brass tag L.S.6745.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with  
 the Land Surveyors' Act on October 11 1996.

Signed [Signature] L.S. or R.C.E. Number L.S.6745



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 10-15-1996 and examined  
 and filed 11-2-2008.

Signed [Signature] Title COUNTY SURVEYOR



County Surveyor's Comment \_\_\_\_\_

